



Technical Service Bulletin

Cobra Moto, LLC

240 Uran Street
Hillsdale, Michigan 49242

(517) 437-9100 phone
(517) 437-9101 fax

November 13, 2017

Power Valve Cable CX65 2013-2014

The power valve cable ECC60164 used on CX65 from 2013 – 2014 is no longer available.

Customers needing this cable will need to upgrade their valve, cable, and plunger to the newer, more reliable, link style valve and plunger assembly, EAC60035.