



# Technical Service Bulletin

Cobra Moto, LLC  
240 Uran Street  
Hillsdale, Michigan 49242

(517) 437-9100 phone  
(517) 437-9101 fax


July 7, 2022

## TSB1222 Rear Brake Master

Due to supply issues, Cobra motorcycle's may have one of two different rear brake master cylinders. Each has a different rebuild kit.



Rebuild kit  
BCKG0015 (11.0mm)



Rebuild kit  
BKC60009 (12.9mm)



Rebuild kit  
BKMU0011 (11.0mm)

