



## Technical Service Bulletin

### **Cobra Motorcycle Mfg.**

240 Uran street  
Hillsdale, MI 49242

(517) 437-9100 phone  
(517) 437-9101 fax

## TSB0722 Factory Works Cylinders

ECMU0661 Factory Works cylinders (EKMU0661 cylinder kit) has become obsolete. The 2022 Factory Works cylinder ECMU0761 (EKMU0761 cylinder kit) will now be the service replacement cylinder for all Factory Works models.