



## Technical Service Bulletin

**Cobra Moto, LLC**

240 Uran Street  
Hillsdale, Michigan 49242

(517) 437-9100 phone  
(517) 437-9101 fax

March 22, 2021

### TSB0821 Factory Works Cylinders

Factory Works cylinders ECMU0461 and ECMU0561 have become obsolete. Customers requiring either of these cylinders will be substituted an ECMU0661 cylinder.