



Technical Service Bulletin

Cobra Moto, LLC

240 Uran Street
Hillsdale, Michigan 49242

(517) 437-9100 phone
(517) 437-9101 fax

April 14, 2022

TSB0922 Steering Stop Bumpers

New steering stop bumpers are available that offer more resistance for keeping fork leg from encountering the radiators. Same part number FCMU0170 and they should be installed with **HCBB1416** Button Head screws as the old HCBC0416 Socket Head Screws can leave marks in the frame.



New Bumper



Old Bumper